

FIRE SAFETY AUDITS IN HIGH RISE BUILDINGS CARRIED OUT BY R. R. NAIR AND HIS TEAM

- (01)** Comprehensive Fire Safety Audit at '**Williams Building**' of **Christian Medical College Hospital**, Vellore, Tamil Nadu – A specialty high rise hospital having **Basement + Ground + 5 Floors** exclusively for Research and Laboratories (September 2019).
- (02)** Comprehensive Fire Safety Audit at '**O Block**' of **Christian Medical College Hospital**, Vellore, Tamil Nadu – A specialty high rise hospital having **Basement + Ground + 6 Floors** (September 2019).
- (03)** Comprehensive Fire Safety Audit at '**A Block**' of **Christian Medical College Hospital**, Vellore, Tamil Nadu – A specialty high rise hospital having **Basement + Ground + 9 Floors** exclusively for Private and Semi Private Patients (September 2019).
- (04)** Comprehensive Fire Safety Audit at '**ISSCC Building**' of **Christian Medical College Hospital**, Vellore, Tamil Nadu – A specialty high rise hospital having **Basement + Ground + 7 Floors** exclusively for Women and Children (September 2019).
- (05)** Fire Safety On-Site Assessment at **The Eye Foundation, Coimbatore, Tamil Nadu** – A specialty high rise hospital having **7 floors** and basement (March 2019).
- (06)** Fire Safety On-Site Assessment at **The Eye Foundation, Tirupur, Tamil Nadu** – A specialty high rise hospital having **5 floors** and basement (March 2019).
- (07)** Fire Safety On-Site Assessment at **The Eye Foundation, Coimbatore, Tamil Nadu** – A specialty high rise hospital having **7 floors** and basement (November 2018).
- (08)** Fire Safety On-Site Assessment at **The Eye Foundation, Tirupur, Tamil Nadu** – A specialty high rise hospital having **5 floors** and basement (November 2018).
- (09)** Fire Safety Audit at **Avalon CHS Ltd., Hiranandani Gardens, Powai, Mumbai** – A residential high rise building consisting of two wings having **33 floors** each (June 2015).
- (10)** Fire Safety Audit at **Florentine CHS Ltd., Hiranandani Gardens, Powai, Mumbai** – A residential high rise building consisting of two wings having **18 floors** each (June 2015).
- (11)** Electrical and Fire Safety Audit at **Asset Reconstruction Co. (India) Ltd. (ARCIL)**, CBD Belapur, **Navi Mumbai** – A commercial complex of **10 floors** (April 2015).
- (12)** Fire Safety Audit at **Maithili's Signet, Vashi, Navi Mumbai** – A commercial high rise building consisting of **14 floors** + Reliance Digital Mall (February-March 2014).
- (13)** Statutory inspection with Form B Certification at **Tejas Heights Co-operative Housing Society, Sion, Mumbai** – A residential high rise building consisting of **11 floors** (2013).

- (14) Statutory inspection with Form B Certification at **Sakar Bhavan, Nariman Point, Mumbai** – A commercial high rise building consisting of **12 floors** (2013).
- (15) Statutory inspection with Form B Certification at **Free Press House, Nariman Point, Mumbai** – A high rise commercial complex consisting of **14 floors** (2013).
- (16) Fire Safety Audit at **Building No. 20 of Mindspace, Hitech City, Cyberabad, Hyderabad**, Andhra Pradesh – A commercial high rise building consisting of **12 floors** - about 10 lacs sq. feet (March 2013).
- (17) Assessments of Fire Safety Requirements for the new high rise building at, **Shrimad Rajchandra Ashram, Dharampur**, Gujarat – (2012).
- (18) Fire Safety Audit at **Florentine, Hiranandani Gardens, Powai, Mumbai** – A residential high rise building consisting of two wings having **18 floors** each (2011).
- (19) Fire Safety Audit at **Jolly Maker Tower 1, Cuffe Parade, Mumbai** – A residential high rise building having Ground + P level + R level + **25 Floors** (2011).
- (20) Fire Safety Audit at **Seva Mandal Educational Society, Matunga, Mumbai** – 3 college buildings consisting of **7 floors** and basement (2010).
- (21) Fire Safety Audit at **Solitaire, Hiranandani Gardens, Powai, Mumbai** – A residential high rise building consisting of **22 floors** (2010).
- (22) Fire Safety Audit at **Odyssey – 1, Hiranandani Gardens, Powai, Mumbai** – A residential high rise building consisting of **27 floors** plus stilt + podium – cum - basement (2010).
- (23) Fire Safety Audit at **Swaminarayan Temple, Ahmedabad**, Gujarat – A complex consisting of 6 buildings (2010).
- (24) Fire Safety Audit at **Free Press House, Nariman Point, Mumbai** – A high rise commercial complex consisting of **14 floors** (2010).
- (25) Fire Safety Audit at **Sakar Bhavan, Nariman Point, Mumbai** – A commercial high rise building consisting of **12 floors** (2009).
- (26) Fire Safety Audit at **Pratiksha Tower, Grant Road, Mumbai** – A residential complex consisting of 3 high rise buildings (Building 'A': **15 floors**, Building 'B': **15 floors**, Building 'C': **12 floors**) (2009).
- (27) Fire Safety Audit at **Jolly High Rise, Bandra, Mumbai** – A residential high rise building consisting of **18 floors** (2009)
- (28) Fire Safety Audit at **Birchwood, Hiranandani Gardens, Powai, Mumbai** – A residential complex consisting of 2 high rise buildings of **16 floors** each (2009).
- (29) Fire Safety Audit at **Blooming Heights, Powai, Mumbai** – A residential high rise building consisting of **19 floors** (2009).
- (30) Fire Safety Audit at **Emgee Greens, Wadala, Mumbai** – A residential complex consisting 3 high rise buildings (Building 'A': **13 floors**, Building 'B': **10 floors**, Building 'C': **10 floors**) (2009).

(31) Fire Safety Audit at **Midtown Apartment, Worli, Mumbai** – A residential high rise building of **19 floors** (2009).